



Angle-Arc® Manual Gouging Torch Parts



Hook-Up Kit & Parts



Torch Assembly Replacement Parts

Item	Description	K3000
	Complete Torch	01-065-001
1	Insulators & Screws	94-433-193
2	Upper Insulator	N/A
3	Lower Insulator	N/A
4	Lever & Screw	94-476-080
5	Valve Bonnet	94-104-016
6	Bonnet Wrench	94-960-001
7	Bonnet Only	94-104-012
8	Spool & O-Rings	94-801-011
9	O-Ring (2 Req'd.)	94-710-036
10	Spool Only	94-801-010
11	Upper Arm	94-048-120
12	Head & Screw	94-378-366
13	Torch Body	94-103-232
14	Hinge Pin	94-632-101
15	Spring	94-800-191
16	Handle	94-370-179

Item	Description	Cat No.
	Complete Hook-Up Kit	94-463-045
1	Male Gouging Connector	94-170-181
2	Cable Boot Cap	94-105-027
3	4-WPC-R Connector	9425-1427
4	Pigtail Air Supply Hose	94-396-205

Cable Assembly Replacement Parts

Item	Description	K3000
	7' (2.1m) Cable Assembly	70-088-107
	10' (3m) Cable Assembly	70-088-110
1	Retainer Screw	94-695-054
2	O-Ring	94-710-027
3	Connector	94-170-178
4	Spring Washer	94-940-104
5	Flat Washer	94-940-103
6	Swivel Sleeve	N/A
7	Clamp (2 Required)	98-167-010
8	7' (2.1m) Conductor	96-130-314
8	10' (3m) Conductor	96-130-315
9	7' (2.1m) Cover	94-171-274
9	10' (3m) Cover	94-171-274
10	Insulating Boot	94-105-014
11	Female Connector	94-170-150

